

Supplemental Type Certificate

Number ST01541LA

This Certificate issued to Global AirWorks
19933 Harrison Ave.
City of Industry, California 91789

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet.*

Original Product Type Certificate Number: A20WE

Make: BOEING

Model: 747-400 Series

Description of Type Design Change: Installation of AirWorks Cockpit Door Surveillance Systems in accordance with FAA Approved AirWorks Index List Document No. IL23006, Revision B, dated June 30, 2003, or later FAA approved revision. AirWorks Airplane Flight Manual Supplement Document No. AFMS232010002, Revision Original, FAA approved on September 15, 2003, or later FAA approved revision, is required as part of this modification.

Limitations and Conditions This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application July 19, 2002

Date reissued: July 29, 2004; Oct. 24, 2006,
September 22, 2009

Date of issuance: October 3, 2003

Date amended:



By direction of the Administrator

Ala W. Shumate
(Signature)

Supervisor, Technical & Administrative Support
Staff, Los Angeles Aircraft Certification Office
(Title)

alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.